Approved For Release 2000/05/31: CIA-RDP89B00551R000600040001-0

25X1A

Dispatch No.



9 April 1956

Page 1 of 1 page


Copy of 4 copies

25X1A

TO:

FROM:

SUBJECT:



DOCUMENT NO. 143316

NO CHANGE IN CLASS.

CLASSIFIED TAIL TS SO 1-06

AUTH: HR 70-2

DATE: 8-1-86 REVIEWER: 100368

1. Detachment "A" A-1006; A-1008

25X1A

These reports will be the same as for

A-1005.

A-1008 had complete camera failure after 200/ miles of tracker film exposed.

No configuration A-2 operations for entire flight due to blown circuit breaker in scope compensator system.

25X1A

Enclosures:

- 1 Documentation of flights (weather)
 Sortie A-1006
 TS #73, copy 1 of 2 (2 pages)
- 2 Documentation of flights (weather) Sortie A-1008 TS #74, copy 1 of 2 (3 pages)

75-143316 TS #72 Copy of 4 page 1 of 1 page